



Fig. 1  
(Prior Art)




*FIG. 2A*



*FIG. 2B*

BEST AVAILABLE COPY



*FIG. 3*







FIG. 4




*FIG. 5*




*FIG. 6*



*FIG. 7*




*FIG. 8*



*FIG. 9*





*FIG. 10*







FIG. 11



*FIG. 12*




*FIG. 13*





*FIG. 14*

chamfer on bone  
 graft profiler tool  
 internal recess?



chamfer on distal  
 region of alignment post?





*FIG. 15A*

*FIG. 15B*


*FIG. 15C*

chamfer (slant) occupying  
 entire roof of bone graft  
 profiler tool internal  
 recess, either without or  
 with chamfer on  
 alignment post




*FIG. 15D*

*FIG. 15E*



*FIG. 16*



*FIG. 17A*









FIG. 17B




*FIG. 17C*




*FIG. 18*



**FIG. 19A**




**FIG. 19B**



BEST AVAILABLE COPY

*FIG. 20*



*FIG. 21*